

DEPARTMENT OF THE AIR FORCE
HEADQUARTERS OGDEN AIR MATERIEL AREA (AFLC)
HILL AIR FORCE BASE, UTAH 84401



REPLY TO
ATTN OF: MML

9 Sep 71

SUBJECT: Equipment Discrepancy ([redacted] 1540 Light Table)

STAT

TO: HQ USAF (AFINYMA, [redacted])

1. Forwarded herewith for your review and evaluation are copies of letters from HQ SAC (INMR) and 544th ARTW (RD). SAC is experiencing considerable difficulty in focusing the Zoom 240 [redacted] stereoscope installed on the [redacted] 1540 light tables.

STAT


2. Since the contracting officer, who has this contract, is located in the Washington area, it is requested that he be contacted for appropriate action through contractual sources to enforce the warranty for Air Force quantities being procured. It is recommended that both the [redacted] [redacted] representatives visit HQ SAC for an on-site inspection, evaluation and corrective action. This should be accomplished at no cost to the Air Force.

STAT

3. ~~Advance arrangements should be made with HQ SAC prior to the representatives from the aforementioned contractors visiting Offutt AFB. If it is the desire of your office, OOAMA will make appropriate arrangements upon receipt of approval from your office and confirmation from the Government Contracting Officer that this can be accomplished at no cost to the government.~~

4. Request this AMA (MML) be advised of action taken on this matter.

FOR THE COMMANDER



2 Atchs

1. HQ SAC (INMR) ltr, 31 Aug 71
2. 544 ARTW (RD) ltr, 23 Aug 71

Cy to: HQ SAC (INMR) w/o atch

USAF review(s) completed.

Declass review by NGA/DoD